


5.00-1 FLOORPLAN - LEVEL 1
1/8"=1'-0"



NOTE:
1. Existing Steel Frame Windows Are To Be Replaced With Steel Frame Windows To Replace Original Steel Windows That Are Missing

KEYNOTES:
10520-A Fire Extinguisher In Fire Panel
Revised Cbs. UL Rated: 204-898C

<p>5.00</p> <p>DATE OF PAGES</p>	<p>CONSTRUCTION DOCUMENTS</p>	<p>THE VANDERGRIFF BLDG. 100 E. DIVISION STREET ARLINGTON, TEXAS</p>	<p>THE ADAPTIVE RE-USE OF: THE VANDERGRIFF BLDG. AS PROFESSIONAL OFFICES</p>		
	<p>REVISIONS</p>				